



R7604A Release Notes

V1.01 - July 16, 2025

Copyright 2025 HighPoint Technologies, Inc.

All rights reserved

Table of Contents

1. Overview	2
1.1. Basic Information	2
1.2. Package Contents	3
2. New Features	4
2.1. Windows Software v1.5.30.0.4 Release	4
2.2. Linux Software v1.8.41.0.0 Release	4
2.3. Linux Software v1.8.40.0.2 Release	4
2.4. Firmware v5.15.12.0 Release	4
3. Known Issues	5
3.1. Windows Software v1.5.30.0.4 Release	5
3.2. Firmware v5.15.12.0 Release	5
4. Install/ Uninstall/ Update the Windows Software	6
4.1. Install the Windows Software	6
4.2. Uninstall the Windows Software	6
4.3. Update the Windows Software	6
5. Install/ Uninstall/ Update the Linux Software	7
5.1. Install the Linux Software	7
5.2. Uninstall the Linux Software	7
5.3. Update the Linux Software	7
6. Update the Firmware	8
6.1. Update the Firmware in the WebGUI	8
6.2. Update the Firmware in the CLI	8
7. Revision History	9
7.1. Version 1.00, April 18, 2025	9
7.2. Version 1.01, July 16, 2025	9

1. Overview

This release notes describe the supported operating systems, new features, resolved issues, known issues, and trouble shooting with the R7604A Release Notes.

The information contained in this document is intended as supplemental information only; it should be used in conjunction with the documentation provided for each component.

1.1. Basic Information

The following table describes the basic information of the the Released Notes.

Table 1-1: Basic Information of the Windows Software Released Notes

Released Component	HighPoint_NVMe_G5_RAID_Windows_Software_HLK_v1.5.30.0.4_25_04_18.zip
Released Contents	● First release of R7604A.
Released Version	Windows Software Version: v1.5.30.0.4 (Driver Version: v1.5.30.0) (RAID Management Version: v3.1.61)
Released Date	04/18/2025
Supported Operating Systems	● Windows 11 ● Windows 10 ● Windows Server 2025 ● Windows Server 2022 ● Windows Server 2019 ● Windows Server 2016 ● Windows Hyper-V Server 2019

Table 1-2: Basic Information of the Linux Software Released Notes

Released Component	HighPoint_NVMe_G5_RAID_Linux_Software_v1.8.41.0.0_25_07_09.tgz
Released Contents	● Support kernel 6.14 and redhat 10.0.
Released Version	Linux Software Version: v1.8.41.0.0 (Driver Version: v1.8.41) (RAID Management Version: v3.2.61)
Released Date	07/16/2025
Supported Operating Systems	● RHEL ● Debian ● Ubuntu ● Fedora ● Proxmox ● Rocky Linux

Table 1-3: Basic Information of the Firmware Released Notes

Released Component	R7604ASSW_Signed_v5.15.12.0_v2.5.1_2025_02_20.zip
Released Contents	● First release of R7604A.
Released Version	v5.15.12.0
Released Date	04/18/2025

1.2. Package Contents

Table 1-4: Package Contents of the Windows Software

Released Component			Description
HighPoint_NVMe_G5_RAID_Windows_Software.exe			Executable file to install RAID software (Driver&Management) for HighPoint NVMe RAID Controller.
Installer Package	Driver	HighPoint NVMe G5 Windows Driver.exe	Driver installation program.
		Readme-Driver.txt	Readme for windows driver.
		x64	Driver to install Windows on the RAID of NVMe RAID Controller.
	Management	HighPoint RAID Management.exe	RAID management installation program.
		Readme-Management.txt	Readme for windows management.
Readme.txt			This file is divided into the following major sections: 1. Software Version 2. Products List 3. Files List 4. Software Installation Guide 5. Software Uninstallation Guide 6. Software Update Guide 7. Known issue 8. Revision History

Table 1-5: Package Contents of the Linux Software

Released Component	Description
setup.bin	Software for NVMe RAID controller.
README.txt	This file is divided into the following major sections: 1. Overview 2. File List 3. Software Version 4. Installation 5. Management Software Usage 6. Driver Uninstallation 7. Management Uninstalltion 8. Driver Revision History 9. Management Revision History 10. Technical Support And Service

Table 1-6: Package Contents of the Firmware

Released Component	Description
R7604ASSW_Signed_vx.x.x.x_202x_xx_xx.blf	Firmware file.
Readme.txt	This file is divided into the following major sections: 1. Software Version 2. Files List 3. Product List 4. Revision History 5. UEFI Revision History

2. New Features

2.1. Windows Software v1.5.30.0.4 Release

The following table lists the new features introduced with the Windows Software v1.5.30.0.4.

Date	Release Version	New Feature
04/18/2025	v1.5.30.0.4	● First release of R7604A.

2.2. Linux Software v1.8.41.0.0 Release

The following table lists the new features introduced with the Linux Software v1.8.41.0.0.

Date	Release Version	New Feature
07/16/2025	v1.8.41.0.0	● Support kernel 6.14 and redhat 10.0.

2.3. Linux Software v1.8.40.0.2 Release

The following table lists the new features introduced with the Linux Software v1.8.40.0.2.

Date	Release Version	New Feature
04/18/2025	v1.8.40.0.2	● First release of R7604A.

2.4. Firmware v5.15.12.0 Release

The following table lists the new features introduced with the Firmware v5.15.12.0.

Date	Release Version	New Feature
04/18/2025	v5.15.12.0	● First release of R7604A.

3. Known Issues

3.1. Windows Software v1.5.30.0.4 Release

The following table lists the known issues introduced with the Windows Software v1.5.30.0.4.

Table3-1: Hibernation fails or not work in BootRAID

Title	Hibernation fails or not work in BootRAID
Description	Hibernation fails or not work when the system is installed on a NVMe RAID, this bug will affect fast startup and sleep.
Workaround	Please use administrator privileges to turn off hibernation with the following command: powercfg /h off

Table3-2: No Sensor Information on WebGUI-Physical in the MicrosoftEdge Browser

Title	No Sensor Information on WebGUI-Physical in the MicrosoftEdge Browser
Description	Open the collected index.xml file using the MicrosoftEdge Browser. No sensor information is displayed on the WebGUI-Physical.
Workaround	This issue is browser related. Please just change to Google Chrome.

3.2. Firmware v5.15.12.0 Release

The following table lists the known issues introduced with the Firmware v5.15.12.0.

Table3-3: The R7604A on the ASUS PRIME X870-P WIFI encounters issues after waking from sleep and hibernation

Title	The R7604A on the ASUS PRIME X870-P WIFI encounters issues after waking from sleep and hibernation
Description	The R7604A on the ASUS PRIME X870-P WIFI motherboard, in Windows 10, disk fails after sleep wakeup, WebGUI does not connect properly after hibernation wakeup.
Workaround	1. Power on the system, and enter the BIOS. 2. Find Advanced→AMD PBS→Graphics Features, set D3Cold Support to Enabled.

4. Install/ Uninstall/ Update the Windows Software

The following sections describe how to install, uninstall, and update the Windows Software.

4.1. Install the Windows Software

To install the HighPoint RAID Software on the Windows operating system, perform the following steps.

1. Locate the HighPoint RAID Software download and open the file.
2. Double-click **HighPoint NVMe G5 RAID Windows Software.exe**.
3. Select the optional components you wish to install. Click **Install** to start the installation.
4. Click **Finish** to reboot Windows.

4.2. Uninstall the Windows Software

The software should be uninstalled from the "Programs and Features" in the Control

1. Panel or the "Apps & Features" in the Settings.
2. Please select "**HighPoint NVME RAID Driver**" and click uninstall. And reboot the system if prompted.
3. Please select "**HighPoint RAID Management**" and click uninstall. And reboot the system if prompted.

4.3. Update the Windows Software

To update the NVMe RAID software, run the **HighPoint_NVMe_G5_RAID_Windows_Software.exe**.

5. Install/ Uninstall/ Update the Linux Software

The following sections describe how to install, uninstall, and update the Linux Software.

5.1. Install the Linux Software

To install the HighPoint RAID Software on the Linux operating system, perform the following steps.

1. Enter the following command to extract the HighPoint RAID Software package:
#tar zxvf HighPoint_NVMe_G5_Linux_Software_vx.x.xx_xx_xx_xx.tar.gz
2. Enter the following command to install the HighPoint RAID Software.
#sh setup.bin (or ./setup.bin)
3. The system will prompt you to restart to make the driver take effect. Manually restart the system.

5.2. Uninstall the Linux Software

1. Enter the following command to uninstall the driver, and press **Y/y** to confirm.
#hptuninhptnvme
2. Enter the following command to uninstall the RAID management, and press **Y/y** to confirm.
#hptuninhptsvr
3. Manually reboot the system.

5.3. Update the Linux Software

To update the NVMe RAID software, run the **setup.bin**.

6. Update the Firmware

The following sections describe how to update the firmware in the WebGUI and CLI.

6.1. Update the Firmware in the WebGUI

To update the firmware in the WebGUI, perform the following steps.

1. Open the **WebGUI**.
2. Click the **Physical→Enclosure#** tab.
3. Click **Choose File** to select the file with a suffix of blf.
4. Click **Check**.
5. Select **Confirm** to flash the selected firmware.
6. Reboot the system to make the update take effect.

6.2. Update the Firmware in the CLI

This command allows you to select the blf file to update the AIC firmware and the UEFI HII Utility version. The process may take some time.

HPT CLI>update {controller_id enclosure_id} fw={file path}

Input example:

```
HPT CLI>update 1/E1 fw=C:\Users\test\Desktop\R7604ASSW_HLK_v5.15.11.0_v2.4.1_2025_02_19.blf
```

7. Revision History

7.1. Version 1.00, April 18, 2025

1. Initial version.
2. Windows Software V1.5.30.0.4 Released.
3. Linux Software v18.40.0.2 Released.
4. Firmware v5.15.12.0 Released.

7.2. Version 1.01, July 16, 2025

Linux Software v1.8.41.0.0 Released.